



SEAT TRIM PARTS



BBS

BSFT = BACK SEAT FRONT "T"
 BSFC = BACK SEAT FRONT CORNER L/R
 BSS = BACK SEAT SIDE
 BSHC = BACK SEAT HINGE COVER
 BSR = BACK SEAT REAR

TBS = TOP BACK SEAT
 BBS = BOTTOM BACK SEAT
 ST = SIDE OF TOP A = A CORNER
 B = CENTER CORNER
 1/2 MOON = LARGE CURVES = L:2



BSR

SEAT TRIM PARTS COST:

BACK (REST) SEAT PARTS:

TOP TBS... \$80
 SIDE OF TOP (ST L OR R)... \$35 Each
 SEAT SIDE 1/2 MOON LARGE CURVE... \$49 Each
 BOTTOM BBS... \$80
 SEAT LITTLE CORNERS A = \$38 X 4
 SEAT LITTLE CORNERS B = \$38 X 4
 SEAT LATCH PARTS PER REQUEST

BOTTOM SEAT PARTS:

FRONT "T" BSFT...\$115
 SEAT REAR BSR... \$80
 FRONT CORNERS BSFC... \$55 Each
 SIDE BSS = L OR R... \$40 Each
 HINGE CORNERS BSHC L OR R... \$55 Each
 SEAT LITTLE CORNERS B = \$38 X 4
 PONTIAC SEAT/CARGO TRIM AVAILABLE
**** CALL FOR PRICE QUOTE ****

We are the original manufacturer of Classic Nomad Stainless Steel Trim.

Please call or email us for our list of custom fabricated stainless steel products made to your specifications.

Below is a Specification Sheet for the trim, please kindly wait for it to load. Thanks!

We also have available:

1955 - 1957 Nomad
 cargo trim
 1955 - 1957 Safari (Pontiac) cargo trim
 1955 - 1957 2 & 4 door wagon cargo trim

QUALITY AUTO REPAIR
 RANDALL BOYCE
 1755 OAKS AVENUE
 MARSHALLTOWN, IA 50158
www.qualityauto56.com